BOTTOM HOLE ASSURANCE, INC.

No. DIR 41924ST-23

NDE Inspection Services

Email: BHAInc@bottomholeassurance.com
107 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964
Bottomholeassurance.com

CUSTOMER HALLIBURTON ICC ☐ 3RD PARTY | FACILITY / LOCATION SERVICE TOOLS | AUTHORIZED BY JASON CLOSTIO | INVOICE NO.

RIG | PROJECT IN HOUSE | P.O. / JOB # 1017510021 | DATE: 4/19/2024

OCS-G & WELL

								PIN									BOX										
Serial #	Tool Description	Overall Length	Fishing Neck Length	Tong Space	Pin I.D.	Pin O.D.	Box O.D.	Connection Size	Pin Length	Pin Cylinder Diameter	Pin Nose Diameter	Pin Relief Diameter	Pin Rel. Width Pin Neck Lgth	Bevel Diameter	B S R	OK or Reject	Remarks	Connection Size	Counter Bore Length	Counter Bore Diameter	Bore Back Dia. Float Bore Dia.	Bore Back Lgth Float Bore Lgth	Box Thread Length	Counterbore Wall Thickness	Bevel Diameter	B S R	OK or Reject	Remarks
EQ# 14070355	9 5/8" Intercept Retrevable Bridge Plug																											
AJA2307616-01	DRAG BLOCK SLEEVE SAP# 102748988							INT INT								Acc Acc												
AC2213715-01	Lower Drag Block RET. SAP# 102748989																	INT									Acc	
BAC23A0925-5	Upper Drag Block RET. SAP# 102748990																	INT									Acc	
4954064-1 (3)	SPLIT RING Collar-Acc SAP# 102620076							*								Acc												
AKV2315090-04	LOWER ADAPTER SAP# 102620077	1.45	-	16 11/16	3 1/2	6 5/8	-	NC 50	4 1/2				5/16	6 1/16		Acc		INT									Acc	
GC2342550-3	J-SLOT MANDREL SAP# 102620078							INT INT								Acc Acc												
AEK2311637	LH Ratchet Thread Man. SAP# 102620079							INT INT								Acc Acc		INT(P)									Acc	
BDX2318171-1	LOWER SHOE SAP# 102620080							*								Acc												
0004929869-3	UPPER ADAPTER SAP# 102620081	1.50	14 3/4	-	-	-	6 5/8	INT(B)								Acc		5 1/4 CAS									Acc	
AFJ237024-2	Lower Mandrel Connector SAP# 102620074							INT (B)								Acc		INT									Acc	
GC2342582-1	Packer Element Mandrel SAP# 102620075							INT								Acc												
BBU237145-04	Packer Element Man. Ret SAP# 102489304																	INT									Acc	

Remarks: FULL BODY INSP. AS PER MAN-GL-HAL-HCT-900 REV 6.3

Customer Rep Signoff:

Batch # Info.

20-B 23K007
Dry Powder
7-HF
White Contrast
14-A

Connection Inspection

Wet Flour. M.P.I.	☑	Dry M.P.I.	☐
Vis. Liq. Pen.	☐	Residual	☐
Flour Liq. Pen.	☐	Continuous	☑
Long. Insp.	☑	AC Current	☐
Trans. Insp.	☑	DC Current	☑

Body Inspection

Wet Flour. M.P.I.	☑	Residual	☐
Vis. Liq. Pen.	☑	Continuous	☐
Flour Liq. Pen.	☐	AC Current	☐
Long. Insp.	☑	DC Current	☑
Trans. Insp.	☑	Visible M.P.I.	☐

Body Dry M.P.I

Dry M.P.I.	☐	Residual	☐
Long. Insp.	☐	Continuous	☐
Trans. Insp.	☐	AC Current	☐
		DC Current	☐

Blacklight Inspection

Blacklight Intensity: 4645 Bath Mixture: 0.25 Whitelight: 0.1

Liquid Penetrant Inspection

Magnaflux Developer: SKD-S2
Batch # 20M06K
Dwell Time: 10 min
White Light: 100fc
Magnaflux Penetrant: ☑ SKL-WP2
(Check one) ☐ ZL-60D
Batch # 22B06C
Dwell Time: 20 min

System Effectiveness: LP-Comparitive Block ☑ Dry MP-Castrol Strip ☐ Wet MP-Castrol Strip ☑ Profile Gage RSC OK ☑

Equipment / Inspector Information

Equipment Used From Unit # 23
Qual. Date(s) MT 4/26/2019 PT 4/26/2019
Level II Inspector: BRANSON THERIOT

Job Information

B BT V BT D BT P DP

3rd Party Rep

Signature: RAYMOND DUNCAN

Signature: Branson Theriot

Signature guarantees final walk thru of job and job site

NDT APPROVED

By david.patin@bottomholeassurance.com at 8:09:27 AM, 4/22/2024

BOTTOM HOLE ASSURANCE, INC.

No. DIR 41924ST-24

NDE Inspection Services

Email: BHAInc@bottomholeassurance.com
107 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964
Bottomholeassurance.com

CUSTOMER HALLIBURTON ICC ☐ 3RD PARTY | FACILITY / LOCATION SERVICE TOOLS | AUTHORIZED BY JASON CLOSTIO | INVOICE NO.

RIG | PROJECT IN HOUSE | P.O. / JOB # 1017510021 | DATE: 4/19/2024

OCS-G & WELL

								PIN										BOX													
Serial #	Tool Description	Overall Length	Fishing Neck Length	Tong Space	Pin I.D.	Pin O.D.	Box O.D.	Connection Size	Pin Length	Pin Cylinder Diameter	Pin Nose Diameter	Pin Relief Diameter	Pin Rel. Width Pin Neck Lgth	Bevel Diameter	B S R	OK or Reject	Remarks	Connection Size	Counter Bore Length	Counter Bore Diameter	Bore Back Dia. Float Bore Dia.	Bore Back Lgth Float Bore Lgth	Box Thread Length	Counterbore Wall Thickness	Bevel Diameter	B S R	OK or Reject	Remarks
EQ# 14070355	9 5/8" Intercept Retrevable Bridge Plug																											
BAC23A0954-3	Upper Adapter Retainer SAP# 102620073																	INT									Acc	
0004922343-3	TOP WEDGE SAP# 102620521							INT								Acc												
AHY2318599-3	SLIP CAGE SAP# 102687136							*								Acc												
4922341-2	UPPER SHOE SAP# 102620527							INT								Acc		INT									Acc	
4922339-1	BOTTOM WEDGE SAP# 102620529							INT								Acc												
5016774-1	Mech.SlipBody SubAssy SAP# 102620539																	INT									Acc	
AHY2318906-2	(5) Internal LH Thread SAP# 102620087							*								Acc												
ATX231581A-4,8,10, 16,15,1,24,26	(8) Bidirectional Slip Seg. SAP# 102620088							*								Acc												
4923434-7,22 ,18,20,13,10	MECH. SLP-Acc SAP# 101615279							*								Acc												
4966196-100	DRAG BLOCK -Acc SAP# 102530303							*								Acc												
4947194-31,2,62,110, 27,16,32,106,80	DRAG BLOCK -Acc SAP# 102530303							*								Acc												

Remarks: FULL BODY INSP. AS PER MAN-GL-HAL-HCT-900 REV 6.3

Customer Rep Signoff:

Batch # Info.

20-B 23K007
Dry Powder
7-HF
White Contrast
14-A

Connection Inspection

Wet Flour. M.P.I.	☑	Dry M.P.I.	☐
Vis. Liq. Pen.	☐	Residual	☐
Flour Liq. Pen.	☐	Continuous	☑
Long. Insp.	☑	AC Current	☐
Trans. Insp.	☑	DC Current	☑

Body Inspection

Wet Flour. M.P.I.	☑	Residual	☐
Vis. Liq. Pen.	☑	Continuous	☐
Flour Liq. Pen.	☐	AC Current	☐
Long. Insp.	☑	DC Current	☑
Trans. Insp.	☑	Visible M.P.I.	☐

Body Dry M.P.I

Dry M.P.I.	☐	Residual	☐
Long. Insp.	☐	Continuous	☐
Trans. Insp.	☐	AC Current	☐
		DC Current	☐

Blacklight Inspection

Blacklight Intensity: 3772 Bath Mixture: 0.25 Whitelight: 0.1

Liquid Penetrant Inspection

Magnaflux Developer: SKD-S2
Batch # 20M06K
Dwell Time: 10 min
White Light: 100fc
Magnaflux Penetrant: ☑ SKL-WP2
(Check one) ☐ ZL-60D
Batch # 22B06C
Dwell Time: 20 min

System Effectiveness: LP-Comparitive Block ☑ Dry MP-Castrol Strip ☐ Wet MP-Castrol Strip ☑ Profile Gage RSC OK ☑

3rd Party Rep

Job Information

B BT V BT D BT P DP

Signature: RAYMOND DUNCAN

Equipment / Inspector Information

Equipment Used From Unit # 23
Qual. Date(s) MT 4/26/2019 PT 4/26/2019
Level II Inspector: BRANSON THERIOT
Signature: Branson Theriot
Signature guarantees final walk thru of job and job site

By david.patin@bottomholeassurance.com at 8:09:19 AM, 4/22/2024