



BOTTOM HOLE ASSURANCE, INC.

NDE Inspection Services

Email: BHAInc@bottomholeassurance.com
 107 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964
 Bottomholeassurance.com

CUSTOMER HALLIBURTON ICC 3RD PARTY
 RIG _____
 OCS-G & WELL _____

FACILITY / LOCATION SERVICE TOOLS
 PROJECT CHEVRON

AUTHORIZED BY JASON CLOSTIO
 P.O. / JOB # 909175712

INVOICE NO. _____
 DATE: 4/22/2024

Serial #	Tool Description	Overall Length	Fishing Neck Length	Tong Space	Pin I.D.	Pin O.D.	Box O.D.	PIN										BOX																					
								Connection Size	Pin Length	Pin Cylinder Diameter	Pin Nose Diameter	Pin Relief Diameter	Pin Rel. Width	Pin Neck Lgth	Bevel Diameter	B S R	OK or Reject	Remarks	Connection Size	Counter Bore Length	Counter Bore Diameter	Counter Bore Diameter	Bore Back Dia. Float Bore Dia.	Bore Back Lgth Float Bore Lgth	Box Thread Length	Counterbore Wall Thickness	Bevel Diameter	B S R	OK or Reject	Remarks									
EQ# 12817309 G3403206-4	PORTED SUB SAP# 102192863	2.87	-	-	3 1/2	6 1/4	6 1/4																NC 50	5/8	5 5/16	-	-	-	-	6 1/16	-	Acc	RE-INSP						

Remarks: CONNECTION INSP AS PER MAN-GL-HAL-HCT-900 REV. 6.3 (MACHINE SHOP CONNECTION INSPECTION ONLY) Customer Rep Signoff: _____

Batch # Info.	Connection Inspection	Body Inspection	Body Dry M.P.I.	Blacklight Inspection	Liquid Penetrant Inspection
20-B 23K007	Wet Flour. M.P.I. <input checked="" type="checkbox"/> Dry M.P.I. <input type="checkbox"/> Dry Powder <input type="checkbox"/> Vis. Liq. Pen. <input type="checkbox"/> Residual <input type="checkbox"/> 7-HF <input type="checkbox"/> Flour Liq. Pen. <input type="checkbox"/> Continuous <input checked="" type="checkbox"/> White Contrast <input type="checkbox"/> Long. Insp. <input checked="" type="checkbox"/> AC Current <input type="checkbox"/> 14-A <input type="checkbox"/> Trans. Insp. <input checked="" type="checkbox"/> DC Current <input checked="" type="checkbox"/>	Wet Flour. M.P.I. <input type="checkbox"/> Residual <input type="checkbox"/> Vis. Liq. Pen. <input type="checkbox"/> Continuous <input type="checkbox"/> Flour Liq. Pen. <input type="checkbox"/> AC Current <input type="checkbox"/> Long. Insp. <input type="checkbox"/> DC Current <input type="checkbox"/> Trans. Insp. <input type="checkbox"/> Visible M.P.I. <input type="checkbox"/>	Dry M.P.I. <input type="checkbox"/> Residual <input type="checkbox"/> Long. Insp. <input type="checkbox"/> Continuous <input type="checkbox"/> Trans. Insp. <input type="checkbox"/> AC Current <input type="checkbox"/> DC Current <input type="checkbox"/>	Blacklight Intensity: 2559 Bath Mixture: 0.25 Whitelight: 0.1 Equipment / Inspector Information Equipment Used From Unit # 23 Qual. Date(s) MT 4/26/2019 PT 4/26/2019	Magnaflux Developer: SKD-S2 Batch # _____ Dwell Time: _____ min White Light: Magnaflux Penetrant: <input type="checkbox"/> SKL-WP2 (Check one) <input type="checkbox"/> ZL-60D Batch # _____ Dwell Time: _____ min
System Effectiveness: LP-Comparative Block <input type="checkbox"/> Dry MP-Castrol Strip <input type="checkbox"/> Wet MP-Castrol Strip <input checked="" type="checkbox"/> Profile Gage RSC OK <input checked="" type="checkbox"/>			3rd Party Rep _____ Signature: <u>RAYMOND DUNCAN</u>		
Job Information B _____ BT _____ V _____ BT _____ D _____ P _____ BT _____			Level II Inspector: BRANSON THERIOT Signature: <u>Branson Theriot</u> Signature guarantees final walk thru of job and job site 		

By david.patin@bottomholeassurance.com at 8:25:40 AM, 4/23/2024