

BOTTOM HOLE ASSURANCE, INC.

NDE Inspection Services

Email: BHAInc@bottomholeassurance.com
107 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964
Bottomholeassurance.com



CUSTOMER Halliburton 3RD PARTY
RIG _____
OCS-G & WELL _____

FACILITY / LOCATION Sperry Drilling
PROJECT _____

AUTHORIZED BY Kale Veronie
P.O. / JOB # 909194492

INVOICE NO. _____
DATE: 4/24/2024

Serial #	Tool Description	Overall Length	Fishing Neck Length	Tong Space	Pin I.D.	Pin O.D.	Box O.D.	PIN										BOX										Remarks				
								Connection Size	Pin Length	Pin Cylinder Diameter	Pin Nose Diameter	Pin Relief Diameter	Pin Neck Lgth	Pin Rel. Width	Bevel Diameter	B S R	OK or Reject	Remarks	Connection Size	Counter Bore Length	Counter Bore Diameter	Bore Back Dia. Float Bore Dia.	Bore Back Lgth	Float Bore Lgth	Box Thread Length	Counterbore Wall Thickness	Bevel Diameter		B S R	OK or Reject	Remarks	
SN: 12764223 PN: 102617706	4 3/4" HANG OFF COLLAR	8.93			2 5/8	4 3/4	4 3/4	NC38	3 15/16						5/16	6 51/64		OK		NC38	5/8	4 1/16							4 41/64		Rej	Damaged Threads
SN: 13094428 PN: 101330431	4 3/4" ILS SUB	5.18		15 15/16	2 9/16	4 21/32		NC 38	3 15/16						9/32	3 59/64		OK		NC38	5/8	4 1/16						4 9/16		Rej	Damaged Shoulder	
								BLADES										OK	*N1													