BOTTOM HOLE ASSURANCE, INC.

No. DIR 42524B6

NDE Inspection Services

Email: BHAInc@bottomholeassurance.com
107 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964
Bottomholeassurance.com

CUSTOMER Halliburton ☐ 3RD PARTY
RIG
OCS-G & WELL

FACILITY / LOCATION Sperry Drilling
PROJECT

AUTHORIZED BY AJ Latiolais
P.O. / JOB # 908271711

INVOICE NO.
DATE: 4/25/2024

								PIN										BOX										
Serial #	Tool Description	Overall Length	Fishing Neck Length	Tong Space	Pin I.D.	Pin O.D.	Box O.D.	Connection Size	Pin Length	Pin Cylinder Diameter	Pin Nose Diameter	Pin Relief Diameter	Pin Rel. Width Pin Neck Lgth	Bevel Diameter	B S R	OK or Reject	Remarks	Connection Size	Counter Bore Length	Counter Bore Diameter	Bore Back Dia. Float Bore Dia.	Bore Back Lgth Float Bore Lgth	Box Thread Length	Counterbore Wall Thickness	Bevel Diameter	B S R	OK or Reject	Remarks
SN:14089008 PN:102907220	PAD															OK												
SN:14089010 PN:102907220	PAD															OK												
SN:14089012 PN:102907220	PAD															OK												
SN:13889983 PN:102774822	PAD HOUSING															OK												
SN:14081119 PN:102774822	PAD HOUSING															OK												
SN:14081122 PN:102774822	PAD HOUSING															OK												
SN:13965184 PN:102775603	PAD BOLT															OK												
SN:13970623 PN:102775603	PAD BOLT															OK												
SN:13970636 PN:102775603	PAD BOLT															OK												
SN:13970653 PN:102775603	PAD BOLT															OK												
SN:13970663 PN:102775603	PAD BOLT															OK												
SN:13971139 PN:102775603	PAD BOLT															OK												

Remarks: Inspection as per D00685901 Rev. W NOTE: All API connections show evidence of Cold Work unless otherwise noted.

Customer Rep Signoff:

Batch # Info.

20-B	
Dry Powder	
7-HF	
White Contrast	
14-A	

Connection Inspection

Wet Flour. M.P.I.	☐	Dry M.P.I.	☐
Vis. Liq. Pen.	☑	Residual	☐
Flour Liq. Pen.	☐	Continuous	☐
Long. Insp.	☐	AC Current	☐
Trans. Insp.	☐	DC Current	☐

Body Inspection

Wet Flour. M.P.I.	☐	Residual	☐
Vis. Liq. Pen.	☑	Continuous	☐
Flour Liq. Pen.	☐	AC Current	☐
Long. Insp.	☐	DC Current	☐
Trans. Insp.	☐	Visible M.P.I.	☐

Body Dry M.P.I

Dry M.P.I.	☐	Residual	☐
Long. Insp.	☐	Continuous	☐
Trans. Insp.	☐	AC Current	☐
		DC Current	☐

System Effectiveness: LP-Comparitive Block ☑ Dry MP-Castrol Strip ☐ Wet MP-Castrol Strip ☐ Profile Gage RSC OK ☑

3rd Party Rep

Job Information

B V D P

Signature:

Blacklight Inspection

Blacklight Intensity: Bath Mixture: Whitelight:

Equipment / Inspector Information

Equipment Used From Unit # 14
Qual. Date(s) MT 7/21/2019 PT 7/30/2021

Level II Inspector: Ridge Albert

Signature: Ridge Albert

Signature guarantees final walk thru of job and job site

Liquid Penetrant Inspection

Magnaflux Developer: SKD-S2
Batch # 23M08C
Dwell Time: 10 min
White Light: 100+
Magnaflux Penetrant: (Check one) ☑ SKL-WP2 ☐ ZL-60D
Batch # 23L075
Dwell Time: 20 min