BOTTOM HOLE ASSURANCE, INC.

No. DIR 42624ST-17

NDE Inspection Services

Email: BHAInc@bottomholeassurance.com
107 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964
Bottomholeassurance.com

CUSTOMER HALLIBURTON ICC ☐ 3RD PARTY | FACILITY / LOCATION SERVICE TOOLS | AUTHORIZED BY JASON CLOSTIO | INVOICE NO.

RIG | PROJECT CANTIUM | P.O. / JOB # 908926916 | DATE: 4/26/2024

OCS-G & WELL

								PIN										BOX										
Serial #	Tool Description	Overall Length	Fishing Neck Length	Tong Space	Pin I.D.	Pin O.D.	Box O.D.	Connection Size	Pin Length	Pin Cylinder Diameter	Pin Nose Diameter	Pin Relief Diameter	Pin Rel. Width Pin Neck Lgth	Bevel Diameter	B S R	OK or Reject	Remarks	Connection Size	Counter Bore Length	Counter Bore Diameter	Bore Back Dia. Float Bore Dia.	Bore Back Lgth Float Bore Lgth	Box Thread Length	Counterbore Wall Thickness	Bevel Diameter	B S R	OK or Reject	Remarks
EQ# 12074031	9 5/8" FD WLK																											
G2725113-10	SETTING SLEEVE SAP# 100073747																	INT									Acc	
G2710358-5	TENSION MANDREL SAP# 100073748																	INT									Acc	

Remarks: FULL BODY INSP AS PER MAN-GL-HAL-HCT-900 REV. 6.3 | Customer Rep Signoff:

Batch # Info.

20-B	23K007
Dry Powder	
7-HF	
White Contrast	
14-A	

Connection Inspection

Wet Flour. M.P.I.	☑	Dry M.P.I.	☐
Vis. Liq. Pen.	☐	Residual	☐
Flour Liq. Pen.	☐	Continuous	☑
Long. Insp.	☑	AC Current	☐
Trans. Insp.	☑	DC Current	☑

Body Inspection

Wet Flour. M.P.I.	☑	Residual	☐
Vis. Liq. Pen.	☐	Continuous	☑
Flour Liq. Pen.	☐	AC Current	☐
Long. Insp.	☑	DC Current	☑
Trans. Insp.	☑	Visible M.P.I.	☐

Body Dry M.P.I

Dry M.P.I.	☐	Residual	☐
Long. Insp.	☐	Continuous	☐
Trans. Insp.	☐	AC Current	☐
		DC Current	☐

System Effectiveness: LP-Comparitive Block ☐ Dry MP-Castrol Strip ☐ Wet MP-Castrol Strip ☑ Profile Gage RSC OK ☑

3rd Party Rep

Job Information

B BT | V BT | D | P BT

Signature:

Blacklight Inspection

Blacklight Intensity: 2176 | Bath Mixture: 0.25 | Whitelight: 0.1

Equipment / Inspector Information

Equipment Used From Unit # 23

Qual. Date(s) MT 4/26/2024 PT 4/26/2024

Level II Inspector: BRANSON THERIOT

Signature: Signature guarantees final walk thru of job and job site

Liquid Penetrant Inspection

Magnaflux Developer: SKD-S2

Batch #

Dwell Time: min

White Light:

Magnaflux Penetrant: ☐ SKL-WP2 (Check one) ☐ ZL-60D

Batch #

Dwell Time: min

By david.patin@bottomholeassurance.com at 9:02:34 AM, 4/29/2024

DCH187924 8/9/23

DCH187924 4/1/23

DCH187924 5/15/22

Page 1.1 Component Trace Number Log Sheet

Assembly Description:	FAS DRILL, Baker #20 WLK, 9 5/8" - 13 3/8"	SAP Part No. / Legacy Part No.	100073746 (802.99630)	Serial Number	Laf 0601 12074031

Component Description				Original Trace No.	Change #1 Trace No. Date		Change #2 Trace No. Date		Change #3 Trace No. Date	
Print Item Number	SAP Part Number	Legacy Part Number	Description	IN SAP						
1C	100073747	802.99631	Setting Sleeve	G2725113-10						
2C	100073748	802.99632	Tension Mandrel	G2710358-5						

All components identified as "critical" in accordance with HCT Technology procedure 21.3.205 (Identification and Assignment of Critical Parts and Inspection Matrices) are indicated with the letter "C" behind the Print Item #.

426245T-17

Cantium

90892