BOTTOM HOLE ASSURANCE, INC.

No. DIR 42924ST-1

NDE Inspection Services

Email: BHAInc@bottomholeassurance.com
107 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964
Bottomholeassurance.com

CUSTOMER HALLIBURTON ICC ☐ 3RD PARTY | FACILITY / LOCATION SERVICE TOOLS | AUTHORIZED BY JASON CLOSTIO | INVOICE NO.

RIG | PROJECT ARENA | P.O. / JOB # 909200294 | DATE: 4/29/2024

OCS-G & WELL

								PIN										BOX											
Serial #	Tool Description	Overall Length	Fishing Neck Length	Tong Space	Pin I.D.	Pin O.D.	Box O.D.	Connection Size	Pin Length	Pin Cylinder Diameter	Pin Nose Diameter	Pin Relief Diameter	Pin Rel. Width Pin Neck Lgth	Bevel Diameter	B S R	OK or Reject	Remarks	Connection Size	Counter Bore Length	Counter Bore Diameter	Bore Back Dia. Float Bore Dia.	Bore Back Lgth Float Bore Lgth	Box Thread Length	Counterbore Wall Thickness	Bevel Diameter	B S R	OK or Reject	Remarks
EQ# 12562967	6 5/8"-8 5/8" EZ WLK																											
G3308393-05	SETTING SLEEVE SAP#100072777																	INT									Acc	
3308433-06	TENSION MANDREL SAP# 100072778							INT								Acc		INT									Acc	

Remarks: FULL BODY INSP AS PER MAN-GL-HAL-HCT-900 REV. 6.3 | Customer Rep Signoff:

Batch # Info.

20-B	23K007
Dry Powder	
7-HF	
White Contrast	
14-A	

Connection Inspection

Wet Flour. M.P.I.	☑	Dry M.P.I.	☐
Vis. Liq. Pen.	☐	Residual	☐
Flour Liq. Pen.	☐	Continuous	☑
Long. Insp.	☑	AC Current	☐
Trans. Insp.	☑	DC Current	☑

Body Inspection

Wet Flour. M.P.I.	☑	Residual	☐
Vis. Liq. Pen.	☐	Continuous	☑
Flour Liq. Pen.	☐	AC Current	☐
Long. Insp.	☑	DC Current	☑
Trans. Insp.	☑	Visible M.P.I.	☐

Body Dry M.P.I

Dry M.P.I.	☐	Residual	☐
Long. Insp.	☐	Continuous	☐
Trans. Insp.	☐	AC Current	☐
		DC Current	☐

Blacklight Inspection

Blacklight Intensity: 5579 Bath Mixture: 0.25 Whitelight: 0.1

Liquid Penetrant Inspection

Magnaflux Developer: SKD-S2
Batch #
Dwell Time: min
White Light:
Magnaflux Penetrant: ☐ SKL-WP2 (Check one) ☐ ZL-60D
Batch #
Dwell Time: min

Equipment / Inspector Information

Equipment Used From Unit # 23
Qual. Date(s) MT 4/26/2024 PT 4/26/2024
Level II Inspector: BRANSON THERIOT
Signature: Signature guarantees final walk thru of job and job site

APPROVED

System Effectiveness: LP-Comparitive Block ☐ Dry MP-Castrol Strip ☐ Wet MP-Castrol Strip ☑ Profile Gage RSC OK ☑

3rd Party Rep

Job Information

B BT V BT D P BT

Signature:

By david.patin@bottomholeassurance.com at 4:30:02 PM, 4/29/2024

9092200294 ARENA

Page 1.1 Component Trace Number Log Sheet

42924ST-1

Assembly Description:	EZSV, Baker #20 WLK, 6 5/8" - 8 5/8"	SAP Part No. / Legacy Part No.	100072779 (802.00019)	Serial Number	12562967

Component Description				Original Trace No.	Change #1 Trace No. Date		Change #2 Trace No. Date		Change #3 Trace No. Date	
Print Item Number	SAP Part Number	Legacy Part Number	Description	IN SAP	Mark Lewis H256648 4/29/24					
1C	100072777	802.00016	Setting Sleeve	G3308393-05						
2C	100072778	802.00018	Tension Mandrel	G3344872-01	2479446-3	1/2/20	3308433-06	7/11/21		
4/29/24	BHA verified	B. Theriot								

SDP