



**BOTTOM HOLE ASSURANCE, INC.**

NDE Inspection Services

No. IR 43024TT-3

Email: BHAInc@bottomholeassurance.com  
107 Citron Drive • Youngsville, LA 70592



Office: (337) 857-8994 Fax: (337) 857-8964  
Bottomholeassurance.com

CUSTOMER HALLIBURTON ICC		3rd PARTY <input type="checkbox"/>	FACILITY / LOCATION TEST TOOLS	AUTHORIZED BY BOBBY CHOATE		INVOICE NO.	
RIG		OCS-G & WELL NO.		PROJECT IN HOUSE	P.O. NO. / JOB NO. 1017510022	DATE 4/30/2024	
SERIAL NO.	DESCRIPTION		PIN	BOX	I.D.	O.D.	LENGTH
1	EQ# 10919842	5" BELOW PACKER SAFTEY JOINT					
2	AEZ152107-4	TOP ADAPTER - ACC		INT (B) - ACC	3 7/8" CAS - ACC	2 1/4	5 1/16 0.92
3		SAP# 100065376					
4	BBM195101.1	MANDREL - ACC		INT x INT - ACC			
5		SAP100065373					
6	1517066-4	SHEAR SET - ACC					
7		SAP# 100065841					
8	B1464860-1	SHEAR SET HOLDER - ACC			INT x INT - ACC		
9		SAP# 100065375					
10	BAC1857433-1	LUGGED PISTON - ACC		INT - ACC			
11		SAP# 100065370					
12	BAC1955493-1	SPLINED OPERATING PISTON - ACC		INT - ACC			
13		SAP# 100065368					
14	AHY2217051-1	OIL CASE - ACC			INT x INT - ACC		
15		SAP# 100065372					
16	BAC22A2131-1	SPLINED NIPPLE - ACC		INT x INT - ACC	INT - ACC		
17		SAP# 100065369					
18	0004184677-1	BOTTOM NIPPLE - ACC		3 7/8" CAS - ACC	INT - ACC	2 1/4	5 1.10
19		SAP# 100065371					
20	KM-1430549-1	TOP LUG ADAPTER - ACC		INT x INT - ACC			
21		SAP# 100065374					
22							
23							
24							
25							
26							
27							
28							
29							
30							
31							
32							
33							
34							
35							
36							
37							
38							
39							
40							

SUMMARY: FULL BODY INSP. BSM-GOM-HAL-TT-201 REV. 6

Batch # Info.	Connection Inspection		Body Inspection		Body Dry M.P.I	
20-B 23K007	Wet Flour. M.P.I. <input checked="" type="checkbox"/>	Dry M.P.I. <input type="checkbox"/>	Wet Flour. M.P.I. <input checked="" type="checkbox"/>	Residual <input type="checkbox"/>	Dry M.P.I. <input type="checkbox"/>	Residual <input type="checkbox"/>
Dry Powder	Vis. Liq. Pen. <input type="checkbox"/>	Residual <input type="checkbox"/>	Vis. Liq. Pen. <input type="checkbox"/>	Continuous <input checked="" type="checkbox"/>	Long. Insp. <input type="checkbox"/>	Continuous <input type="checkbox"/>
7-HF	Flour Liq. Pen. <input type="checkbox"/>	Continuous <input checked="" type="checkbox"/>	Flour Liq. Pen. <input type="checkbox"/>	AC Current <input type="checkbox"/>	Trans. Insp. <input type="checkbox"/>	AC Current <input type="checkbox"/>
White Contrast	Long. Insp. <input checked="" type="checkbox"/>	AC Current <input type="checkbox"/>	Long. Insp. <input checked="" type="checkbox"/>	DC Current <input checked="" type="checkbox"/>		DC Current <input type="checkbox"/>
14-A	Trans. Insp. <input checked="" type="checkbox"/>	DC Current <input checked="" type="checkbox"/>	Trans. Insp. <input checked="" type="checkbox"/>	Visible M.P.I. <input type="checkbox"/>		

System Effectiveness: LP-Comparitive Block  Dry MP-Castrol Strip  Wet MP-Castrol Strip

Blacklight Inspection	Equipment / Inspector Information
Blacklight Intensity: 3948 Bath Mixture: 0.25 Whitelight: 0.1	Equipment Used From Unit # 13 Qual. Date(s) MT 2/16/2023 PT 8/9/2023
<b>Liquid Penetrant Inspection</b> Whitelight: _____ Magnaflux Developer: SKD-S2 Magnaflux Penetrant: (Check one) <input type="checkbox"/> SKL-WP2 <input type="checkbox"/> ZL-60D Batch # _____ Batch # _____ Dwell Time: _____ min Dwell Time: _____ min	3rd Party Rep: _____ Signature: _____ Level II Inspector: BRONZE POIRIER Signature: 
<b>Job Information</b> B _____ BP _____ V _____ BP _____ D _____ P _____ BP _____	Signature:  <small>Signature guarantees final walk thru of job and job site</small>
	Customer Rep Signoff: 