



BOTTOM HOLE ASSURANCE, INC.

NDE Inspection Services

No. IR 43024TT-6

Email: BHAInc@bottomholeassurance.com
107 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964
Bottomholeassurance.com

CUSTOMER HALLIBURTON ICC		3rd PARTY <input type="checkbox"/>	FACILITY / LOCATION TEST TOOLS	AUTHORIZED BY BOBBY CHOATE		INVOICE NO.	
RIG		OCS-G & WELL NO.		PROJECT IN HOUSE	P.O. NO. / JOB NO. 1017510022	DATE 4/30/2024	
SERIAL NO.	DESCRIPTION		PIN	BOX	I.D.	O.D.	LENGTH
1	10255229	7 5/8 CHAMP PACKERS					
2							
3	B3438314-3	BOTTOM ADAPTER - ACC		3 7/8" CAS - ACC		2 1/2	4 3/4" 2.25
4		SAP# 102018706					
5							
6	CK1446100-25	HYDRAULIC ROUND SLIPS - ACC					
7		SAP#100012598					
8	BBM226943-2	PORTED HOUSING - ACC		INT - ACC			
9		SAP# 100004113					
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							
31							
32							
33							
34							
35							
36							
37							
38							
39							
40							

SUMMARY: FULL BODY INSP. BSM-GOM-HAL-TT-201 REV. 6 ***COMPONENTS ONLY***

Batch # Info.	Connection Inspection		Body Inspection		Body Dry M.P.I	
20-B 23K007	Wet Flour. M.P.I. <input checked="" type="checkbox"/>	Dry M.P.I. <input type="checkbox"/>	Wet Flour. M.P.I. <input checked="" type="checkbox"/>	Residual <input type="checkbox"/>	Dry M.P.I. <input type="checkbox"/>	Residual <input type="checkbox"/>
Dry Powder	Vis. Liq. Pen. <input type="checkbox"/>	Residual <input type="checkbox"/>	Vis. Liq. Pen. <input type="checkbox"/>	Continuous <input checked="" type="checkbox"/>	Long. Insp. <input type="checkbox"/>	Continuous <input type="checkbox"/>
7-HF	Flour Liq. Pen. <input type="checkbox"/>	Continuous <input checked="" type="checkbox"/>	Flour Liq. Pen. <input type="checkbox"/>	AC Current <input type="checkbox"/>	Trans. Insp. <input type="checkbox"/>	AC Current <input type="checkbox"/>
White Contrast	Long. Insp. <input checked="" type="checkbox"/>	AC Current <input type="checkbox"/>	Long. Insp. <input checked="" type="checkbox"/>	DC Current <input checked="" type="checkbox"/>		DC Current <input type="checkbox"/>
14-A	Trans. Insp. <input checked="" type="checkbox"/>	DC Current <input checked="" type="checkbox"/>	Trans. Insp. <input checked="" type="checkbox"/>	Visible M.P.I. <input type="checkbox"/>		

System Effectiveness: LP-Comparative Block Dry MP-Castrol Strip Wet MP-Castrol Strip

Blacklight Inspection	Equipment / Inspector Information
Blacklight Intensity: <u>4158</u> Bath Mixture: <u>0.25</u> Whitelight: <u>0.1</u>	Equipment Used From Unit # <u>13</u> Qual. Date(s) MT <u>2/16/2023</u> PT <u>8/9/2023</u>
Liquid Penetrant Inspection Whitelight: _____ Magnaflux Developer: SKD-S2 Magnaflux Penetrant: (Check one) <input type="checkbox"/> SKL-WP2 <input type="checkbox"/> ZL-60D Batch # _____ Batch # _____ Dwell Time: _____ min Dwell Time: _____ min	3rd Party Rep: _____ Signature: _____ Level II Inspector: BRONZE POIRIER Signature: <u>Bronze Poirier</u> <small>Signature guarantees final walk thru of job and job site</small>
Job Information B _____ BP _____ V _____ BP _____ D _____ P _____ BP _____	Customer Rep Signoff: _____



FORM		Halliburton Management System			
Title: Component Log Sheet		Document Number: FO-GOM-HAL-TSS-905			
Region: GOM		Function/ PSL: TSS			
Owner: HMS Team	TSS	Approved By: Charles Haydell	Job Revision By: Kenneth Constantine	Rev Date: 09.Jan.2023	Rev No: 5.0
					Page 1 of 5

1. Current Component Trace Number Log Sheet

Assembly Description:	7 5/8 -in. 20-39 lb Casing, CHAMP® IV Packer	SAP Part No. / Legacy Part No.	102036789	SAP Tool Number	10255229
-----------------------	--	--------------------------------	-----------	-----------------	----------

Legend: MTR Tracker:	MTR in Tool File >	Part changed / Waiting on MTR >	MTR not Available. Need to track >
----------------------	--------------------	---------------------------------	------------------------------------

Print Item Number	SAP Part Number	Revision	Description	Original Trace Number	Date Replaced	Current Trace Number	Date Reviewed
1	100071685		Top Adapter	N/A		C-3931311-1	4/22/24 MM
2	100004100		Upper Mandrel	N/A		BBM216288-2	4/22/2024 MM
3	100071677		Hydraulic Slip Body	N/A		C-3990667-1	4/22/2024 MM
6	100012598		Round Hydraulic Slip (4)	N/A		CK1848615-12 CK1345580-101 CK1647770-83 ck1846636-16 CK1446100-25	4/30/24 LD
6	100012598		Round Hydraulic Slip (4)	N/A		4285315-105,67BDT2219236-19 B4515556-20	4/22/2024 MM
7	100004101		Hydraulic Slip Holding Strap (4)	N/A		AN1976484 (4)	4/22/2024 MM
8	100012595		Floating Piston	N/A		AHY147269-2	4/22/2024 MM
9	100004114		Balancing Coupling	N/A		C-3506423-3	4/22/2024 MM
10	100004113		Ported Housing	N/A		BBM226943-2	4/30/24 LD
11	100071683		Upper Body			BAS 1749-1	4/22/2024 MM
12	100004115		Bypass Sleeve			ZU1323886-19	4/22/2024 MM
13	100004116		Center Mandrel			B 1900991	4/22/2024 MM
14	100071678		Shoe Coupling			B-1357504-14	4/22/2024 MM
15	100012603		Packer Mandrel			AKV149503-4	4/22/2024 MM
16	100071672		6.35 OD Backup Ring			C2735884-5	Not Use
16	101973729		6.62 OD Backup Ring			C3714849-36	4/22/2024 MM
17	100071673		6.35 OD Lower Shoe			BBM184376-1	Not Use
17	101973728		6.62 OD Lower Shoe			C3714846-2	4/22/2024 MM
18	100012607		Mechanical Slip Body			3237366-4	4/22/2024 MM
19	100012556		Mechanical Slip (6)			AN1433D99-112/156/109/108/76/51	4/22/2024 MM
20	100070232		Split Ring Collar			BBM184357-1	4/22/2024 MM
21	100004034		Drag Block Sleeve			ALQ13698-8	4/22/2024 MM
22	100070524		Drag Block (4)			AN1872932 AN187529-16/13/14	4/22/2024 MM
25	102018706		3 7/8 CAS Lower Mandrel			B3438314-3	4/30/24 LD

43024TT-6