# BOTTOM HOLE ASSURANCE, INC.

No. DIR 11025SB13


*NDE Inspection Services*

Email: BHAInc@bottomholeassurance.com
107 Citron Drive • Youngsville, LA 70592

**Office: (337) 857-8994 Fax: (337) 857-8964**
**Bottomholeassurance.com**


CUSTOMER SBES ☐ 3RD PARTY | FACILITY / LOCATION SHOP | AUTHORIZED BY KEITH | INVOICE NO.

RIG | PROJECT | P.O. / JOB # 327503523 | DATE: 1/10/2025

OCS-G & WELL

| | | | | | | | | PIN | | | | | | | | | | BOX | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Serial # | Tool Description | Overall Length | Fishing Neck Length | Tong Space | Pin I.D. | Pin O.D. | Box O.D. | Connection Size | Pin Length | Pin Cylinder Diameter | Pin Nose Diameter | Pin Relief Diameter | Pin Rel. Width Pin Neck Lgth | Bevel Diameter | B S R | OK or Reject | Remarks | Connection Size | Counter Bore Length | Counter Bore Diameter | Bore Back Dia. Float Bore Dia. | Bore Back Lgth Float Bore Lgth | Box Thread Length | Counterbore Wall Thickness | Bevel Diameter | B S R | OK or Reject | Remarks |
| S/N 14157505 P/N 102855122 | 9 1/2" X-BAT | 20.66 | | | N/A | | 9 1/2 | | | | | | | | | | | 7 5/8 REG | 11/16 | 7 1/16 | | | | | 8 51/64 | | OK | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | MR 54770 | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

**Remarks:** INSP. AS PER D00685901 REV. V MARKED WITH CW STAMP UNLESS OTHERWISE NOTED | Customer Rep Signoff:

**Batch # Info.**

| | |
|---|---|
| 20-B | |
| Dry Powder | |
| 7-HF | |
| White Contrast | |
| 14-A | |

**Connection Inspection**

| | | | |
|---|---|---|---|
| Wet Flour. M.P.I. | ☐ | Dry M.P.I. | ☐ |
| Vis. Liq. Pen. | ☑ | Residual | ☐ |
| Flour Liq. Pen. | ☐ | Continuous | ☐ |
| Long. Insp. | ☐ | AC Current | ☐ |
| Trans. Insp. | ☐ | DC Current | ☐ |

**Body Inspection**

| | | | |
|---|---|---|---|
| Wet Flour. M.P.I. | ☐ | Residual | ☐ |
| Vis. Liq. Pen. | ☑ | Continuous | ☐ |
| Flour Liq. Pen. | ☐ | AC Current | ☐ |
| Long. Insp. | ☐ | DC Current | ☐ |
| Trans. Insp. | ☐ | Visible M.P.I. | ☐ |

**Body Dry M.P.I**

| | | | |
|---|---|---|---|
| Dry M.P.I. | ☐ | Residual | ☐ |
| Long. Insp. | ☐ | Continuous | ☐ |
| Trans. Insp. | ☐ | AC Current | ☐ |
| | | DC Current | ☐ |

System Effectiveness: LP-Comparitive Block ☑ Dry MP-Castrol Strip ☐ Wet MP-Castrol Strip ☐ Profile Gage RSC OK ☑

3rd Party Rep

**Job Information**

B | V TB | D TB | P TB

Signature:

**Blacklight Inspection**

Blacklight Intensity: | Bath Mixture: | Whitelight:

**Equipment / Inspector Information**

Equipment Used From Unit # 25

Qual. Date(s) MT | PT 1/27/2020

Level II Inspector: TANNER BLANCHARD

Signature:

Signature guarantees final walk thru of job and job site

**Liquid Penetrant Inspection**

Magnaflux Developer: SKD-S2
Batch # 23F01C
Dwell Time: 10 min
White Light: 190 FC
Magnaflux Penetrant: ☑ SKL-WP2
(Check one) ☐ ZL-60D
Batch # 22B02C
Dwell Time: 20 min