BOTTOM HOLE ASSURANCE, INC.

No. DIR 11525CW-1

NDE Inspection Services

Email: BHAInc@bottomholeassurance.com
107 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964
Bottomholeassurance.com

CUSTOMER Halliburton ICC ☐ 3RD PARTY | FACILITY / LOCATION Clean Well | AUTHORIZED BY Tony Frederick | INVOICE NO.

RIG | PROJECT Shell | P.O. / JOB # 909550671 | DATE: 1/15/2025

OCS-G & WELL

								PIN										BOX													
Serial #	Tool Description	Overall Length	Fishing Neck Length	Tong Space	Pin I.D.	Pin O.D.	Box O.D.	Connection Size	Pin Length	Pin Cylinder Diameter	Pin Nose Diameter	Pin Relief Diameter	Pin Rel. Width Pin Neck Lgth	Bevel Diameter	B S R	OK or Reject	Remarks	Connection Size	Counter Bore Length	Counter Bore Diameter	Bore Back Dia. Float Bore Dia.	Bore Back Lgth Float Bore Lgth	Box Thread Length	Counterbore Wall Thickness	Bevel Diameter	B S R	OK or Reject	Remarks
13620578	Drill Tech	6.70	23 1/4	13 1/8	3"	6 3/4	6 3/4	CTM-57	5.624.	5.839.				6.740.		Acc		CTM-57		5.928.			5.628.	0.417.	6.743.		Acc	
13328997	Drill Tech	5.81	18 3/8	17 1/8	3"	6 3/4	6 3/4	CTM-57	5.623.	5.838.				6.737.		Acc		CTM-57		5.930.			5.628.	0.402.	6.733.		Acc	
13551219	Bull Nose	1.72	-	-	-	-	6 5/8											NC 50	5/8	5 5/16					6 15/32		Acc	

Remarks: FULL BODY INSP AS PER BSD-GL-HAL-CWT-201 Rev. 15 | Customer Rep Signoff:

Batch # Info.

20-B	23K007
Dry Powder	
7-HF	
White Contrast	
14-A	

Connection Inspection

Wet Flour. M.P.I.	☑	Dry M.P.I.	☐
Vis. Liq. Pen.	☐	Residual	☐
Flour Liq. Pen.	☐	Continuous	☑
Long. Insp.	☑	AC Current	☐
Trans. Insp.	☑	DC Current	☑

Body Inspection

Wet Flour. M.P.I.	☑	Residual	☐
Vis. Liq. Pen.	☐	Continuous	☑
Flour Liq. Pen.	☐	AC Current	☐
Long. Insp.	☑	DC Current	☑
Trans. Insp.	☑	Visible M.P.I.	☐

Body Dry M.P.I

Dry M.P.I.	☐	Residual	☐
Long. Insp.	☐	Continuous	☐
Trans. Insp.	☐	AC Current	☐
		DC Current	☐

System Effectiveness: LP-Comparitive Block ☐ Dry MP-Castrol Strip ☐ Wet MP-Castrol Strip ☑ Profile Gage RSC OK ☑

Job Information

B GR V GR D P GR

3rd Party Rep

Signature:

Blacklight Inspection

Blacklight Intensity: 5626 Bath Mixture: 0.25 Whitelight: 0.1

Equipment / Inspector Information

Equipment Used From Unit # 32

Qual. Date(s) MT 11/30/2021 PT

Level II Inspector: GAELEN ROBIN

Signature: Gaelen Robin

Signature guarantees final walk thru of job and job site

Liquid Penetrant Inspection

Magnaflux Developer: SKD-S2

Batch #

Dwell Time: min

White Light:

Magnaflux Penetrant: ☐ SKL-WP2 (Check one) ☐ ZL-60D

Batch #

Dwell Time: min

APPROVED

E-DIR01-06

By david.patin@bottomholeassurance.com at 8:04:38 AM, 1/16/2025