BOTTOM HOLE ASSURANCE, INC.

No. DIR 11525HMM1

NDE Inspection Services

Email: BHAInc@bottomholeassurance.com
107 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964
Bottomholeassurance.com

CUSTOMER HALLIBURTON ☐ 3RD PARTY
RIG WEST BOREAS
OCS-G & WELL WB004

FACILITY / LOCATION HMM SHOP / CLEANWELL OUTGOING
PROJECT SHELL WEST BOREAS

AUTHORIZED BY HEATH
P.O. / JOB # SO# 909806775

INVOICE NO.
DATE: 1/15/2025

								PIN									BOX										
Serial #	Tool Description	Overall Length	Fishing Neck Length	Tong Space	Pin I.D.	Pin O.D.	Box O.D.	Connection Size	Pin Length	Pin Cylinder Diameter	Pin Nose Diameter	Pin Relief Diameter	Pin Rel. Width Pin Neck Lgth	Bevel Diameter	B S R	OK or Reject	Remarks	Connection Size	Counter Bore Length	Counter Bore Diameter	Bore Back Dia. Float Bore Dia.	Bore Back Lgth Float Bore Lgth	Box Thread Length	Counterbore Wall Thickness	Bevel Diameter	B S R	OK or Reject	Remarks
HMM 853	6.5" LH SPIRAL MILL	6.09	20 3/4	23 1/2	2 1/2	5"	5"	XT39	4.497	4.072	3.550			4.795		OK		XT39		4.144			4.500	.437	4.807		OK	

	☐	☑	☐	☐	☑	☐	☐	☐	☐		
	☐	☐	☐	☐	☑	☐	☐	☐	☐		
7-HF	Flour Liq. Pen.	☐	Continuous	☑	Flour Liq. Pen.	☐	AC Current	☐	Trans. Insp.	☐	AC Current	☐
White Contrast	Long. Insp.	☑	AC Current	☐	Long. Insp.	☑	DC Current	☑			DC Current	☐
14-A	Trans. Insp.	☑	DC Current	☑	Trans. Insp.	☑	Visible M.P.I.	☐				

System Effectiveness: LP-Comparitive Block ☐ Dry MP-Castrol Strip ☐ Wet MP-Castrol Strip ☑ Profile Gage RSC OK ☑

3rd Party Rep

Job Information

B JC V JC D P JC

Signature:

Equipment / Inspector Information

Equipment Used From Unit # 24
Qual. Date(s) MT 10/20/2023 PT
Level II Inspector: JAYDE CHAMPEAUX
Signature:
Signature guarantees final walk thru of job and job site

Dwell Time: min
White Light:
Magnaflux Penetrant: ☐ SKL-WP2
(Check one) ☐ ZL-60D
Batch #
Dwell Time: min