BOTTOM HOLE ASSURANCE, INC.

No. DIR 11525ST-3

NDE Inspection Services

Email: BHAInc@bottomholeassurance.com
107 Citron Drive • Youngsville, LA 70592

Office: (337) 857-8994 Fax: (337) 857-8964
Bottomholeassurance.com

CUSTOMER HALLIBURTON ICC ☐ 3RD PARTY | FACILITY / LOCATION SERVICE TOOLS | AUTHORIZED BY JASON CLOSTIO | INVOICE NO.
RIG | PROJECT BYRON | P.O. / JOB # 909677445 | DATE: 1/15/2025
OCS-G & WELL

								PIN										BOX									
Serial #	Tool Description	Overall Length	Fishing Neck Length	Tong Space	Pin I.D.	Pin O.D.	Box O.D.	Connection Size	Pin Length	Pin Cylinder Diameter	Pin Nose Diameter	Pin Relief Diameter	Pin Rel. Width Pin Neck Lgth	Bevel Diameter	B S R	OK or Reject	Remarks	Connection Size	Counter Bore Length	Counter Bore Diameter	Bore Back Dia. Float Bore Dia.	Bore Back Lgth Float Bore Lgth	Box Thread Length	Counterbore Wall Thickness	Bevel Diameter	B S R	OK or Reject	Remarks
EQ# 10255394	4 3/4" SSC I VALVE																											
ALC1840037-2	SEAL MANDREL SAP# 100070453	1.31	-	-	2 1/8	-	4 3/4	INT INT(B)								Acc Acc		NC 38	11/16	4 1/16					4 5/8		Rej	PITTED THREADS
ABX1340750-3	UPPER BODY SAP# 100070454							INT								Acc		INT									Acc	
B59353-4	MANDREL RETAINER SAP# 100070455							INT								Acc												
C2982269-1	CIRCULATING BODY SAP# 100070456							INT								Acc		INT									Acc	
B59356-1	Sliding Valve Mandrel- ACC SAP# 100070458							*								Acc												
B2946020-09	SLIDING VALVE- ACC SAP# 100070457							*								Acc												
AFJ133376-4	LOWER BODY SAP# 100070464	1.81	-	-	2 7/16	4 7/8	-	4 5/32 UNS								Acc		INT									Acc	
MISSING	PLUG																											

Remarks: FULL BODY INSP AS PER MAN-GL-HAL-HCT-900 REV. 6.4 - DE- MAGNETIZATION PERFORMED AS PER ES-I-72

Customer Rep Signoff:

Batch # Info.

20-B	23K007
Dry Powder	
7-HF	
White Contrast	
14-A	

Connection Inspection

Wet Flour. M.P.I.	☑	Dry M.P.I.	☐
Vis. Liq. Pen.	☐	Residual	☐
Flour Liq. Pen.	☐	Continuous	☑
Long. Insp.	☑	AC Current	☐
Trans. Insp.	☑	DC Current	☑

Body Inspection

Wet Flour. M.P.I.	☑	Residual	☐
Vis. Liq. Pen.	☐	Continuous	☑
Flour Liq. Pen.	☐	AC Current	☐
Long. Insp.	☑	DC Current	☑
Trans. Insp.	☑	Visible M.P.I.	☐

Body Dry M.P.I

Dry M.P.I.	☐	Residual	☐
Long. Insp.	☐	Continuous	☐
Trans. Insp.	☐	AC Current	☐
		DC Current	☐

System Effectiveness: LP-Comparitive Block ☐ Dry MP-Castrol Strip ☐ Wet MP-Castrol Strip ☑ Profile Gage RSC OK ☑

Blacklight Inspection

Blacklight Intensity: 5381 Bath Mixture: 0.25 Whitelight: 0.1

Equipment / Inspector Information

Equipment Used From Unit # 23
Qual. Date(s) MT 4/26/2024 PT 4/26/2024
Level II Inspector: BRANSON THERIOT
Signature:

Signature guarantees final walk thru of job and job site

Liquid Penetrant Inspection

Magnaflux Developer: SKD-S2
Batch #
Dwell Time: min
White Light:
Magnaflux Penetrant: ☐ SKL-WP2
(Check one) ☐ ZL-60D
Batch #
Dwell Time: min

Job Information

B BT V BT D P BT

3rd Party Rep
Signature:

APPROVED

By david.patin@bottomholeassurance.com at 7:50:15 AM, 1/16/2025